

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S2	5168	"suspended ceiling"	US-PGPUB; USPAT	AND	ON	2007/09/18 11:55
S3	1105	S1 S2	US-PGPUB; USPAT	AND	ON	2007/09/18 11:55
S4	107	S1 S2 replace	US-PGPUB; USPAT	AND	ON	2007/09/18 11:56
S5	0	("modularbuilding").FN.	US-PGPUB; USPAT	OR	OFF	2007/11/08 10:09
S6	0	("modularbuilding").FN.	US-PGPUB; USPAT	OR	OFF	2007/11/08 10:09
S7	0	S6	US-PGPUB; USPAT	AND	ON	2007/11/08 10:10
S8	1613	"modular building"	US-PGPUB; USPAT	AND	ON	2007/11/08 10:10
S9	0	"modular building""0"	US-PGPUB; USPAT	AND	ON	2007/11/08 10:59
S10	19	"6250022"	US-PGPUB; USPAT	AND	ON	2007/11/08 11:03
S11	27	("1229477" "2078011" "2336435" "3500596" "3566554" "4633626" "5331778" "5724774" "5890338" "5975660").FN. OR ("6250022").URFN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 11:13
S12	396	52/79.9	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 13:24
S13	101	52/79.3	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 13:46
S14	161	52/92.1	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 13:52
S15	223	52/92.2	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 13:56
S16	52	52/745.11	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:03
S17	169	52/745.06	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:07
S18	904	52/27	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:11

S19	561	52/79.5	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:23
S20	399	52/36.4	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:31
S21	203	52/36.6	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:33
S22	63	52/81.5	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:35
S23	1372	52/79.1	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:35
S24	356	52/90.1	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:36
S25	208	52/126.3	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:37
S26	504	52/262	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:40
S27	27	("1229477" "2078011" "2336435" "3500596" "3566554" "4633626" "5331778" "5724774" "5890338" "5975660").PN. OR ("6250022").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:42
S28	452	312/100	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:46
S29	1042	312/108	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:47
S30	3038	"tilt up"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:47
S31	21	S30 interengaging	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:48
S32	594	S30 building	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 14:49
S33	257	52/289	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:09
S34	693	"composite building"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:17

S35	83	"composite building" interconnecting	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:17
S36	42	"composite building" interconnecting roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:17
S37	38203	prefab\$	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:24
S38	7727	prefab\$ (building system)	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:24
S39	64	prefab\$ (building system)"tilt-up"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:24
S40	2797	prefab\$ (building system)roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:27
S41	48	prefab\$ (building system) (roof near connecting)	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:28
S42	4	flat near roof "steel girders"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:36
S43	3183	flat adj roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:37
S44	1178	S43 connecting	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:38
S45	736	S44 "building"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:38
S46	3	S43 near steel	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:41
S47	116	S43 girders	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/08 15:42
S48	8233	"roof structure"	US-PGPUB; USPAT	AND	ON	2007/11/09 08:36
S49	283	"roof structure" girders	US-PGPUB; USPAT	AND	ON	2007/11/09 08:37
S50	0	("2003/0172516").URPN.	USPAT	AND	ON	2007/11/09 08:44

S51	30	("3170269" "3350828" "3482367" "3591993" "4037377" "4125984" "4443988" "4837999" "4989386" "5021108" "5121583" "5152114" "5497589" "5638651" "5842315" "6085485").PN. OR ("6256960").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 08:52
S52	0	sna adj in near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:13
S53	0	snap adj in near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:13
S54	0	"snap in" near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:13
S55	0	"lock in" near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:13
S56	60	"interlock" near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:14
S57	32	"modular roof panels"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:19
S58	11	"snap in" roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:26
S59	4	"lock in" roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:26
S60	242786	boss	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:27
S61	8088	boss roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:27
S62	90	boss roof girders	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:27
S63	0	boss roof (prefab4)	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:29
S64	154	boss roof (prefab\$)	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:29
S65	108	"tilt-up construction"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:39

S66	36	waall	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:47
S67	109555	wall roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:47
S68	52226	S67 system	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:47
S69	20441	S67 system (interconnect or engaged or lock)	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:48
S70	4725	S67 system (interconnect)	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:49
S71	1780	S67 system (interconnect)building	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 09:50
S72	551	S67 system (interconnect)building modular	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 10:02
S73	0	("2007/0193186").URPN.	USPAT	AND	ON	2007/11/09 10:02
S74	6938	roof near wall	USPAT	AND	ON	2007/11/09 10:09
S75	22	S74 near (engaging or lock\$ or snap or connect)	USPAT	AND	ON	2007/11/09 10:10
S76	123	52/763	USPAT	AND	ON	2007/11/09 10:12
S77	4	("3182769" "3886705" "4201024").PN. OR ("5896717").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 10:25
S78	100	52/774	USPAT	AND	ON	2007/11/09 10:31
S79	92	52/571	USPAT	AND	ON	2007/11/09 10:35
S80	928	52/698	USPAT	AND	ON	2007/11/09 10:36
S81	297	52/272	USPAT	AND	ON	2007/11/09 10:37
S82	51	52/448	USPAT	AND	ON	2007/11/09 10:49
S83	0	"snap in" near roof	EPO; JPO	AND	ON	2007/11/09 10:50
S84	3	"interlock" near roof	EPO; JPO	AND	ON	2007/11/09 10:54
S85	91	boss roof	EPO; JPO	AND	ON	2007/11/09 10:55
S86	216	walls roof (interlock or \$engageor engage\$ or connect)	EPO; JPO	AND	ON	2007/11/09 10:56

S87	745	walls roof (interlock or \$engage or engage\$ or connect)	EPO; JPO	AND	ON	2007/11/09 11:03
S88	8	walls roof (interlock or \$engage or engage\$ or connect) modular	EPO; JPO	AND	ON	2007/11/09 11:03
S89	8	walls roof (interlock or \$engage or engage\$ or connect) tilt	EPO; JPO	AND	ON	2007/11/09 11:04
S90	2423	"roof Structure"	EPO; JPO	AND	ON	2007/11/09 11:04
S91	34	"roof Structure" (interconnect or \$engage)	EPO; JPO	AND	ON	2007/11/09 11:05
S92	1840	"building construction"	EPO; JPO	AND	ON	2007/11/09 11:06
S93	176	"building construction" roof	EPO; JPO	AND	ON	2007/11/09 11:06
S94	1	"building construction" roof lock	EPO; JPO	AND	ON	2007/11/09 11:07
S95	34	"modular building system"	EPO; JPO	AND	ON	2007/11/09 11:50
S96	15	"engage" roof and wall and projections	EPO; JPO	AND	ON	2007/11/09 11:53
S97	10480	"engage" roof and wall and projections	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 11:54
S98	1202	"engage" roof and wall and projections enclosure	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 11:55
S99	1634	roof near (connect or engage)	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:02
S100	0	S99 near "building construction"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:02
S101	8	S99 near "building"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:03
S102	251	S99 near30 wall	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:04
S103	77	("0603147" "2079635" "2270161" "2981383" "3070646" "3381430" "3436881" "3452501" "3513608" "3516216" "3543456" "3638385" "3640039" "3675380" "3820299" "3854269" "3866381" "3992839" "4258519" "4294051" "4447099" "4557091" "4652170" "4805365" "5036634" "5155961" "5184436" "5221131"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:12

		"5331778" "5372415" "5386788" "5398909" "5413236" "5466058" "5529423" "5575119" "5592794" "5605344" "5622010" "5647181" "5664380" "5673531" "5724774" "5775046" "5813738" "5864997" "5975660" "6047663" "6053591" "6099092" "6105794" "6113203" "6185878" "6202867" "6250022" "6357194" "D420838").PN. OR ("6701678"). URPN.				
S104	52	("0975692" "1924414" "2751635" "3039569" "3256860" "3299594" "3484999" "3501875" "3512316" "3566554" "3593471" "3643689" "3690077" "3707811" "3838545" "3899043" "3992829" "4102091" "4505078" "4592175" "4637179" "4644708" "4726155" "4822197" "4854094" "5285604").PN. OR ("5724774").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:18
S105	17	("2057942" "2691242" "3442311" "3692201" "3844083" "4035965" "4173287" "4874341" "5118547" "5357728" "5400178" "5895045" "6488153" "6665993").PN. OR ("7155865").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:22
S106	23	("3564786" "3710521" "3754364" "3792558" "3822519" "3824750" "3835601" "3852924" "3881283" "3900994" "3940890" "3982732" "4098039" "4221441" "4398378" "4447996" "4545158" "4807407" "5435476" "5643488" "5782047" "5867964").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:23
S107	18	("5293725").URPN.	USPAT	AND	ON	2007/11/09 12:25

S108	32	("2618039" "3215389" "3372519" "3559944" "3600870" "3706168" "3724143" "3730475" "3750366" "3772835" "3814374" "3847521" "3898776" "3990193" "4038798" "4050213" "4068430" "4127971" "4185423" "4211043" "4240236" "4244682" "4252292" "4650150" "4886234" "5524861" "5643488" "5893241" "6058672").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:27
S109	8	("3074080" "3356183" "3822569" "3990197" "5035077" "5210985").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:28
S110	15	("1653126" "3574981" "3675885" "3700202" "3727885" "3885361" "4068427" "4083156" "4872634" "5322404" "5634301" "5938391" "5943830" "6029407").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:30
S111	29	("2058386" "2357819" "3033330" "3078968" "3111202" "3195191" "3292328" "3494405" "3583466" "3596701" "3823523" "3897668" "3986312" "4471548" "4516620" "4546591" "4612848" "4708189" "5471805" "5487402" "5735100").PN. OR ("6050045"). URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:31
S112	27	("4429850" "4726554" "4805783" "4809479" "5228579" "5409120" "5622010" "5655674" "5775521" "5791093" "5857578" "5890607" "5941026" "5944203" "6098363" "6349507" "6397534" "6763957" "6945414" "7093726" "7104023" "D302086" "D393907" "D404148" "D426089" "D511581" "D533283").PN. OR ("D551470"). URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:32

S113	27	("1229477" "2078011" "2336435" "3500596" "3566554" "4633626" "5331778" "5724774" "5890338" "5975660").PN. OR ("6250022").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:33
S114	9	("2010294" "3529389" "4276730" "4616459" "4896469" "5411782" "6233891").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:34
S115	17	("1321213" "1843112" "2005958" "2110110" "2154390" "4023324" "4058948" "4953332" "5146726" "5373675" "5678378" "5802792").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:36
S116	21	("0152340" "0770050" "0796433" "1181934" "1729935" "2793407" "3090086" "3365222" "3601428" "3683429" "3901611" "3914914" "4005556").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:41
S117	0	("2005/0076605").URPN.	USPAT	AND	ON	2007/11/09 12:43
S118	208	("0518292" "1124404" "1129658" "1131479" "1238858" "1313630" "1363391" "1421007" "1436033" "1439281" "1499572" "1537278" "1592070" "1593424" "1657441" "1725200" "1753451" "1757763" "1773168" "1778345" "1834892" "1840304" "1854633" "1893636" "1934760" "1988124" "1988388" "2006300" "2058285" "2075262" "2111577" "2184464" "2208589" "2228363" "2262127" "2266007" "2306548" "2321813" "2451951" "2467115" "2514805" "2592634" "2630614" "2723107" "2775019" "2780936" "2823426" "2823442" "2902745" "2924962" "2993637" "3146497" "3170269" "3245185" "3246828" "3295818" "3310917" "3317178" "3330437" "3341998" "3380703" "3415023" "3434689" "3435580"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:44

		"3515779" "3529389" "3534515" "3553797" "3623288" "3638902" "3707815" "3818661" "3885008" "3886699" "3892098" "3906665" "3927498" "3930633" "3971172" "3979863" "4005559" "4017051" "4033545" "4090336" "4141532" "4159100" "4163349" "4176504" "4194333" "4241555" "4291513" "4365453" "4380887" "4422997" "4426060" "4432176" "4494353" "4512126" "4532745" "4542613" "4554124" "4570398" "4605529" "4619032" "4624089" "4641468" "4726153" "4726157" "4751803" "4815243" "4841702" "4862660" "4878323" "4934121" "4947600" "4974381" "5055252" "5313753" "5335470" "5357721" "5381635" "5384993" "5398468" "5442887" "5448871").PN. OR ("5560156" "5588272" "5640822" "5697189" "5699639" "5732524" "5865001" "Re15979").PN. OR ("6151843"). URPN.				
S119	20	("1696104" "1820869" "1889138" "2047062" "2467581" "2575758" "2617160" "3236014" "3747290" "4114338" "4872297" "5425207").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:49
S120	19	("3170269" "3350828" "3482367" "3591993" "4037377" "4125984" "4443988" "4837999" "4989386" "5021108" "5121583" "5152114" "5497589" "5638651" "5842315" "6085485").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:52

S121	69	(("20030182886" "2365579" "2915150" "2934180" "3253849" "3662507" "3729889" "3783563" "3791912" "3921355" "4074489" "4078348" "4263762" "4282697" "4455793" "4557091" "4615155" "4621467" "4689926" "4754587" "4777774" "4802319" "4924641" "4974383" "5007222" "5285607" "5287675" "5331782" "5353563" "5412918" "5416139" "5594202" "5676486" "5685124" "5706620" "5735090" "5792539" "5890334" "6006480" "6037033" "6044603" "6092862" "6122877" "6178709" "6250037" "6256959" "6256960" "6314704" "6378264" "6412243" "6413610" "6438923" "6455131" "6481172" "6493995" "6514368" "6564521" "6568582" "6571523" "6574938" "6584740" "6584742" "6591558" "6591567" "6729097").FN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:53
S122	18	(("2785099" "3204383" "3343314" "3835604" "4103674" "4333292" "4391075" "4528790" "4545166" "4637188" "4677903" "4724651" "4735026" "4819397").FN. OR ("5564250").URFN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 12:57
S123	65	(("1763300" "1850118" "1959880" "2067403" "2082138" "2574074" "3304683" "3471981" "3653172" "3787130" "3890755" "4011697" "4054012" "4076432" "4078847" "4142335" "4205497" "4275534" "4305677" "4347015" "4350318" "4356675" "4365453" "4551957").FN. OR ("4688358").URFN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 13:02

S124	38	("2221934" "2990203" "3245188" "3530996" "3532369" "3666298" "3731958" "3858989" "4090798" "4194338").PN. OR ("4577449").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/09 13:06
S125	258	52/289	US-PGPUB; USPAT	AND	ON	2007/11/13 10:45
S126	111	52/285.1	US-PGPUB; USPAT	AND	ON	2007/11/13 11:02
S127	38	("0095504" "0405562" "0676509" "0713871" "1094773" "2793401" "2853751" "2853752" "3018017" "3146011" "3392497" "3679280" "4098199" "4158338" "4266386" "4426935" "4796392" "5212924" "5386788" "5669495" "5724774" "5960592" "6099197" "6120206" "6286269" "RE33263").PN. OR ("6786009").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 11:07
S128	304	52/643	US-PGPUB; USPAT	AND	ON	2007/11/13 11:20
S129	485	52/655.1	US-PGPUB; USPAT	AND	ON	2007/11/13 11:31
S130	503	52/262	US-PGPUB; USPAT	AND	ON	2007/11/13 11:43
S131	18	("3762109" "4018016" "4384317" "4410930" "4718185" "4754582" "5107637" "5363608" "6295767" "6415557" "D250836" "D252215" "D336136" "D338073" "D403434" "D406352" "D436669" "D438635").PN. OR ("7237360").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 11:45
S132	817	52/263	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 12:07
S133	302	52/585.1	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:18
S134	0	("2003/0154672").URPN.	USPAT	AND	ON	2007/11/13 13:21

S135	27	("1830382" "2293569" "2396828" "2600900" "2793401" "3052291" "3308596" "3727355" "3880405" "4873797" "5167246" "5184436" "5579796" "5657583" "5778604" "5921047" "6073404" "6151843" "D404092").PN. OR ("6598363"). URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:23
S136	1238	312/263	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:27
S137	3553	wall near support and roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:29
S138	411	(panel and roof) near support	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:30
S139	8921	panel near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:41
S140	48	"building panel" near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:41
S141	54	("2151420" "2269018" "2592634" "2696102" "3292331" "3566568" "3755982" "3782049" "3988279" "4038798" "4062822" "4075808" "4130536" "4194919" "4249354" "4343125" "4439966" "4523415" "4532745" "4547331" "4550543" "4613649" "4625484" "4641468" "4774794" "4787189" "4862660" "4915539" "4924641" "5081810" "5108679" "5109088" "5123222" "5162060" "5231813" "5252636" "5322562" "5347900" "5353562" "5371990" "5393805" "5485703" "5488806" "5498683" "5519971" "5540020" "5565535" "5566521").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:42

S142	65	("2744042" "2851873" "3310917" "3315424" "3398491" "3446692" "3458609" "3677874" "3803788" "3874139" "3879908" "4006570" "4015387" "4038798" "4047357" "4071984" "4079560" "4090340" "4140824" "4187651" "4226067" "4236361" "4249354" "4250670" "4253288" "4288962" "4297820" "4336676" "4340802" "4342180" "4393636" "4454702" "4455793" "4486993" "4486996" "4489530" "4505019").PN. OR ("4625484"). URFN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:43
S143	24	roof near boss	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:45
S144	24	"steel framed wall"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:47
S145	3	"steel framed panels"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:50
S146	2332	steel framed panels	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:50
S147	196	steel framed panels near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:50
S148	171	steel framed panels near roof (secured or locked or engaged or interconnected)	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 13:51
S149	1	steel framed panels near roof (secured or locked or engaged or interconnected)	EPO; JPO	AND	ON	2007/11/13 13:57
S150	1	"3727355"	EPO; JPO	AND	ON	2007/11/13 14:13
S151	16	"3727355"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 14:13
S152	8	"5758461"	US-PGPUB; USPAT	AND	ON	2007/11/13 14:15
S153	27	"3543456"	US-PGPUB; USPAT	AND	ON	2007/11/13 14:16
S154	2479	"flat roof"	US-PGPUB; USPAT	AND	ON	2007/11/13 14:17

S155	118	link near roof	US-PGPUB; USPAT	AND	ON	2007/11/13 14:46
S156	61	link near roof and walls	US-PGPUB; USPAT	AND	ON	2007/11/13 14:46
S157	462	roof ("lap joints" or "laps splices" or "dove tail joints" or "dowel joints" or "pin fitting joints" or "tongue and groove")	US-PGPUB; USPAT	AND	ON	2007/11/13 14:52
S158	1	S157 wall	US-PGPUB; USPAT	AND	ON	2007/11/13 14:55
S159	301	S157 wall	US-PGPUB; USPAT	AND	ON	2007/11/13 14:55
S160	7541	girders	US-PGPUB; USPAT	AND	ON	2007/11/13 15:59
S161	200	girders near (walls or panels)	US-PGPUB; USPAT	AND	ON	2007/11/13 16:00
S162	150	girders near (walls or panels) (connected or engaged or interconnected)	US-PGPUB; USPAT	AND	ON	2007/11/13 16:00
S163	724	312/265.5	US-PGPUB; USPAT	AND	ON	2007/11/13 16:34
S164	1	"6892498"	US-PGPUB; USPAT	AND	ON	2007/11/13 16:43
S165	22	("20010029712" "20020043038" "2732706" "4698947" "5134826" "5490357" "5860260" "5887401" "5950396" "6006480" "6112473" "6173547" "6185898" "6233892" "6237297" "6305142" "6321496" "6393782" "6401419" "6571523" "6647686").PN. OR ("6892498"). URP.N.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 16:44
S166	19	"6250022"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 16:59
S167	43	("1365753" "1416919" "1477867" "1495439" "1716626" "1835524" "3148230" "3451183" "3511004" "3687512" "3879914" "4099815" "4145854" "4147001" "4162114" "4382046" "4388786" "4683674" "4778309" "4915540" "5155961" "5412918" "5471806" "5493839" "5511345" "5634300" "5647181" "5706620" "5797235" "6099411" "6176053" "6202867"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 17:01

		"6250022" "6250035").PN. OR ("6532707").URPN.				
S168	13	("20030140573" "4570392" "4914874" "5619826" "5647177" "5682622" "5706613" "6115971" "6250022" "6418672" "6581337" "6701678").PN. OR ("6892497").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 17:04
S169	77	("0603147" "2079635" "2270161" "2981383" "3070646" "3381430" "3436881" "3452501" "3513608" "3516216" "3543456" "3638385" "3640039" "3675380" "3820299" "3854269" "3866381" "3992839" "4258519" "4294051" "4447099" "4557091" "4652170" "4805365" "5036634" "5155961" "5184436" "5221131" "5331778" "5372415" "5386788" "5398909" "5413236" "5466058" "5529423" "5575119" "5592794" "5605344" "5622010" "5647181" "5664380" "5673531" "5724774" "5775046" "5813738" "5864997" "5975660" "6047663" "6053591" "6099092" "6105794" "6113203" "6185878" "6202867" "6250022" "6357194" "D420838").PN. OR ("6701678"). URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/13 17:06
S170	1797	"concrete panels"	US-PGPUB; USPAT	AND	ON	2007/11/14 09:08
S171	401	"concrete wall panels"	US-PGPUB; USPAT	AND	ON	2007/11/14 09:08
S172	158	"concrete wall panels" roof	US-PGPUB; USPAT	AND	ON	2007/11/14 09:08
S173	0	"concrete wall panels" roof "direct bearing"	US-PGPUB; USPAT	AND	ON	2007/11/14 09:08
S174	74	"concrete wall panels" roof bearing	US-PGPUB; USPAT	AND	ON	2007/11/14 09:09
S175	26	("0675648" "1796048" "2001162" "2202783" "2208814" "2592634" "2664740" "2703003" "2704935" "3494092" "3555763" "3693308").PN. OR ("3842558").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:21

S176	305	"concrete panels" (connect or engage or mount) roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:27
S177	24	("1519319" "2725241" "3330424" "3655218" "3687300" "3765543" "3765550" "4481743" "4496277" "4531720" "4676713" "5042222" "5333981" "5427495" "5551831" "5690461" "5921738" "5947665" "6341788" "6592319").PN. OR ("6869261").URPN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:34
S178	7	S170 near tilt	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:45
S179	2	S170 near roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:46
S180	88	S170 tilt roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:46
S181	2	S170 near (connect or engage or interconnect or install) roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:48
S182	286	("direct bearing connection") or ("pocket connections")	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:50
S183	16	("direct bearing connection") or ("pocket connections") roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:51
S184	3438	("direct bearing ") or ("pocket connections")	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:52
S185	3168	("direct bearing ") or ("pocket connections") roof	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:52
S186	3155	("direct bearing ") or ("pocket connections") roof concrete	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:52
S187	3155	("direct bearing ") or ("pocket connections") roof concrete panels	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:52
S188	3155	("direct bearing ") or ("pocket connections") roof "concrete panels"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:52
S189	3155	("direct bearing ") or ("pocket connections") roof near "concrete panels"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:53
S190	0	("pocket connections") roof near "concrete panels"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:53

S191	0	("direct bearing") roof near "concrete panels"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:54
S192	0	("direct bearing") roof "concrete panels"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:55
S193	0	("direct bearing") roof "concrete panels"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:55
S194	21	"517689"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:55
S195	0	"517689".pn.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 09:55
S196	16	"5608999"	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 11:40
S197	1	"5865001".pn.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 13:07
S198	140	("0518292" "1124404" "1129658" "1131479" "1238858" "1313630" "1363391" "1421007" "1436033" "1439281" "1499572" "1537278" "1592070" "1757763" "1773168" "1778345" "1834892" "1840304" "2058285" "2111577" "2184464" "2208589" "2266007" "2306548" "2321813" "2451951" "2514805" "2592634" "2630614" "2723107" "2775019" "2823426" "2823442" "2902745" "2924962" "2993637" "3146497" "3245185" "3246828" "3295818" "3310917" "3317178" "3330437" "3380703" "3415023" "3434689" "3435580" "3515779" "3553797" "3638902" "3885008" "3886699" "3892098" "3930633" "3979863" "4017051" "4033545" "4090336" "4141532" "4159100" "4163349" "4194333" "4241555" "4291513" "4365453" "4380887" "4422997" "4426060" "4432176" "4494353")	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 13:46

		"4512126" "4532745" "4542613" "4554124" "4570398" "4605529" "4619032" "4624089" "4641468" "4751803" "4815243" "4841702" "4862660" "4934121" "4947600" "4974381" "5055252" "5313753" "5381635" "5588272" "5697189").PN.				
S199	7	("1124404").URPN.	USPAT	AND	ON	2007/11/14 14:04
S200	14	("3719016").URPN.	USPAT	AND	ON	2007/11/14 14:05
S201	15	("1653126" "3574981" "3675885" "3700202" "3727885" "3885361" "4068427" "4083156" "4872634" "5322404" "5634301" "5938391" "5943830" "6029407").PN.	US-PGPUB; USPAT; USOCR	AND	ON	2007/11/14 14:44

11/14/2007 3:16:16 PM

C:\Documents and Settings\Ebrace\My Documents\EAST\Workspaces\10501451modular building.
wsp